

Software update information

File name: UPD03007.bin

Content

The content of the software update depends on the status of the software installed in your vehicle. See the description below for an overview of the possible content of the update and the devices supported.

The versions contained in this package are as follows:

- ▷ ME-8.5.5, TE-8.5.5

Conditions

The software update is available only for certain vehicles equipped with a USB audio interface. In these vehicles, the main menu "Settings" includes the menu item "Software update". Further information is provided in the Owner's Handbook for Vehicle under Software Update.

Go to www.bmw.com/update or the compatibility matrix at www.bmw.com/bluetooth to find out whether your vehicle is supported.

Installation

Installation of the software update requires agreement with the terms and conditions of use. For further information, see www.bmw.com/update. For the purposes of installation, save the software update file in the main directory of a USB drive. Observe the additional instructions in the Owner's Handbook under Software Update. Following installation of the software update, the new software status is shown in the vehicle under "Show current version".

Notes

Once the software has been updated, the software in the vehicle is restarted and data transferred from the USB drive resynchronised where necessary. Wait a few minutes until the USB drive is operational again. Tracks or playlists played before the software update must be selected again. This is also required when the previous version of the software is restored using "Restore previous version". Linked Bluetooth devices may need to be reconnected after installation or deinstallation.

Software update (ME-8.5.5, TE-8.5.5)

Content

- ▷ Improved speed and stability for multimedia and telephones.
- ▷ Improved music playback from a USB medium or phone connected via the USB audio interface and containing multiple playlists.
- ▷ Improved music search with MTP devices connected, improvements in information display for tracks played back.
- ▷ Improves telephone functions with more stable Bluetooth connections and faster phonebook synchronisation, improved display of received calls.
- ▷ Greater data connection stability for BMW Services with Apple iPhone iOS 6.

Supported devices

The software update improves the compatibility of the following devices:

Multimedia

- ▷ Apple: iPhone 5 (iOS 6.1.3).
- ▷ Sony Ericsson: Xperia Arc S.
- ▷ Nokia: 701.
- ▷ BlackBerry: Bold 9790 (OS 7.1).
- ▷ All USB media.

Phone

- ▷ Apple: iPhone 5 (iOS 6.1.3).
- ▷ Sony Ericsson: Xperia V (4.1.2).
- ▷ Nokia: Lumia 920 (Windows 8).
- ▷ Samsung: Galaxy S III (4.1.2), Galaxy S III mini (4.1.1).
- ▷ HTC: One X+ (4.1.1).
- ▷ Motorola: RAZR HD (4.1.1).
- ▷ BlackBerry: Bold 9900 (OS 7.1), Torch 9810 (OS 7.1), Z 10 (OS 10.0).

Notes

Following installation of the software update, the following software status is shown in the vehicle under Show current version:

- ▷ ME-8.5.5
- ▷ TE-8.5.5