

Information



Sheer Driving
Pleasure



SOFTWARE UPDATE INFORMATION

Congratulations on your choice of a BMW.

The better you are acquainted with your car, the easier you will find it is to handle. We would therefore like to offer you the following advice:

Please read the Owner's Handbook before setting out in your new BMW. Please also read the integrated Owner's Handbook in your vehicle. It contains important notes on how to operate the car, enabling you to derive maximum benefit from the technical advantages of your BMW. It also contains useful information which will help you to uphold both your BMW's operating safety and its full resale value.

This documentation provides you with information on the software update.

We wish you pleasurable, safe driving.

BMW AG

Contents

4	Contents
4	Conditions
4	Installation
4	Notes
5	Software update (TN-2.34.1)
5	Software update (MN-2.18.2, TN-2.18.5)
6	Software update (MN-1.37.3, TN-1.37.10)
6	Software update (MN-1.23.7, TN-1.23.15)
7	Software update (MN-1.21.6, TN-1.21.15)

Software update information

Contents

This document provides you with information on the software update.

The contents of the software update depend on the version of the software installed in your vehicle.

You can find detailed information on the software update and the devices supported in the description below.

One of the following versions will be installed depending on which vehicle you have:

- ▷ TN-2.34.1
- ▷ MN-2.18.2, TN-2.18.5
- ▷ MN-1.37.3, TN-1.37.10
- ▷ MN-1.23.7, TN-1.23.15
- ▷ MN-1.21.6, TN-1.21.15

Conditions

The software update is available only for certain vehicles equipped with a USB audio interface.

Go to www.bmw.com/update or the compatibility matrix at www.bmw.com/bluetooth to find out whether your vehicle is supported.

You will find further information on the software update in the Owner's Handbook Navigation, Entertainment, Communication.

Installation

Installation of the software update requires agreement with the terms and conditions of use.

For further information, see www.bmw.com/update.

For the purposes of installation, save the software update file in the main directory of a USB

device and connect the USB device to the USB audio interface on the centre arm rest.

In addition, read the information in the Owner's Handbook Navigation, Entertainment, Communication under Software Update.

Following installation of the software update, the new software version is displayed in the vehicle:

1. "Settings"
2. "Software update"
3. "Show current version"

Notes

Once the software has been updated, the vehicle must be switched off.

Data transferred from external devices are synchronised, if applicable.

Tracks or playlists played before the software update must be selected again.

This is also necessary when previous versions of the software are restored:

1. "Settings"
2. "Software update"
3. "Restore software"

Manual changes to music files might be deleted if the software is restored or updated by the service partner.

If the following menu item is not displayed correctly after the update, deactivate Bluetooth for a short time during the installation:
"ConnectedDrive"

Software update (TN-2.34.1)

Contents

- ▷ Phone: Restores the BMW Internet via customer SIM function.

Supported devices

The software update improves the compatibility of the following devices:

Phone

- ▷ Apple: Devices running iOS from Version 7.0
- ▷ Samsung: Devices running Android from Version 4.x
- ▷ HTC: Devices running Android from Version 4.x
- ▷ LG: Devices running Android from Version 4.x

Notes

Following installation of the software update, the current software version is displayed in the vehicle:

- ▷ Phone: TN-2.34.1

Software update (MN-2.18.2, TN-2.18.5)

Contents

- ▷ Multimedia: Improved support for bookmarks with audio books.
Improved support of A4A-compatible apps.
Improved marking of the track currently being played when using Apple devices in Japan.
- ▷ Phone: Improved operation with the BlackBerry 9900 and the latest operating system software OS 7.1.

Detailed view of e-mails in vehicle adopts line breaks.

Improved operation with BlackBerry 10.

Incoming messages are transferred to the vehicle more reliably and displayed.

Improved stability with the Motorola Razr i.

Restores the BMW Internet via customer SIM function.

Supported devices

The software update improves the compatibility of the following devices:

Multimedia

- ▷ All USB drives
- ▷ Apple: iPhone 4S, 5 (iOS 6)
- ▷ Apple: All devices (when used in Japan)

Phone

- ▷ Apple: Devices running iOS from Version 7.0
- ▷ BlackBerry: 10, 9900 (OS 7)
- ▷ Motorola: Razr i
- ▷ Samsung: Devices running Android from Version 4.x
- ▷ HTC: Devices running Android from Version 4.x
- ▷ LG: Devices running Android from Version 4.x

Notes

Following installation of the software update, the current software version is displayed in the vehicle:

- ▷ Media: MN-2.18.2
- ▷ Phone: TN-2.18.5

Software update (MN-1.37.3, TN-1.37.10)

Contents

- ▷ Multimedia: Improved support for book-marks with audio books.
- ▷ Phone: Improved Bluetooth connection stability.
Improved display of the sender of SMS messages on iPhone devices with iOS 6.
The end device only communicates the sender name to the vehicle for a sender.
The call-back function is not available and messages cannot be sent, deleted or marked as unread.
Improved behaviour with BlackBerry 9900 and the latest operating software OS 7.1.
E-mail contents are displayed in the vehicle.
Improved stability with the Motorola Razr i.
Restores the BMW Internet via customer SIM function.

Supported devices

The software update improves the compatibility of the following devices:

Multimedia

- ▷ All USB drives

Phone

- ▷ Apple: iPhone 3GS, 4, 4S, 5, 5C, 5S (iOS 6 & iOS 7)
- ▷ BlackBerry: 9900 (OS 7)
- ▷ Motorola: Razr i
- ▷ Samsung: Devices running Android from Version 4.x
- ▷ HTC: Devices running Android from Version 4.x
- ▷ LG: Devices running Android from Version 4.x

Notes

Following installation of the software update, the current software version is displayed in the vehicle:

- ▷ Media: MN-1.37.3
- ▷ Phone: TN-1.37.10

Software update (MN-1.23.7, TN-1.23.15)

Contents

- ▷ Multimedia: Improved operation with video playlists with iPod devices.
Improved music playback and stability for iPod devices or large USB devices.
- ▷ Phone: Improved Bluetooth connection stability.
Improved transfer of contact data of the rear-seat telephone.
Improved call lists in China.
Improved display of the sender of SMS messages on iPhone devices with iOS 6.
The end device only communicates the sender name to the vehicle for a sender.
The three callback functions are not possible, and nor is it possible to send or delete messages or mark them as unread.
Senders and receivers with umlauts in their names are correctly displayed in the vehicle.
Improved behaviour with BlackBerry 9900 and the latest operating software OS 7.1.
E-mail contents are displayed in the vehicle.
Improved stability with the Motorola Razr i.
Restores the BMW Internet via customer SIM function.

Supported devices

The software update improves the compatibility of the following devices:

Multimedia

- ▷ All USB drives
- ▷ Apple: iPod, iPhone 3GS, 4, 4S, 5 (iOS 6)
- ▷ Samsung: Galaxy S3 (Android 2.1.4)

Phone

- ▷ Apple: iPhone 3GS, 4, 4S, 5, 5C, 5S (iOS 6 & iOS 7)
- ▷ Nokia: All devices (when used in China)
- ▷ Samsung: All devices
- ▷ Rear-seat telephone
- ▷ BlackBerry: 9900 (OS 7)
- ▷ Motorola: Razr i
- ▷ HTC: Devices running Android from Version 4.x
- ▷ LG: Devices running Android from Version 4.x

Notes

Following installation of the software update, the current software version is displayed in the vehicle:

- ▷ Media: MN-1.23.7
- ▷ Phone: TN-1.23.15

Software update (MN-1.21.6, TN-1.21.15)

Contents

- ▷ Multimedia: Improved operation with video playlists with iPod devices.
Improved music playback and stability for iPod devices or large USB devices.
- ▷ Phone: Improved Bluetooth connection stability.

Improved transfer of contact data of the rear-seat telephone.

Improved call lists in China.

Improved display of the sender of SMS messages on iPhone devices with iOS 6.

The end device only communicates the sender name to the vehicle for a sender.

The three callback functions are not possible, and nor is it possible to send or delete messages or mark them as unread.

Improved display of senders and receivers with umlauts in their names in the vehicle.

Improved operation with the BlackBerry 9900 and the latest operating software OS 7.1.

E-mail contents are displayed in the vehicle.

Improved stability with the Motorola Razr i.

Restores the BMW Internet via customer SIM function.

Supported devices

The software update improves the compatibility of the following devices:

Multimedia

- ▷ All USB drives
- ▷ Apple: iPod, iPhone 3GS, 4, 4S, 5 (iOS 6)
- ▷ Samsung: Galaxy S3 (Android 2.1.4)

Phone

- ▷ Apple: iPhone 3GS, 4, 4S, 5, 5C, 5S (iOS 6 & iOS 7)
- ▷ Nokia: All devices (when used in China)
- ▷ Samsung: All devices
- ▷ Rear-seat telephone
- ▷ BlackBerry: 9900 (OS 7)
- ▷ Motorola: Razr i
- ▷ HTC: Devices running Android from Version 4.x

- ▷ LG: Devices running Android from Version 4.x

Notes

Following installation of the software update, the current software version is displayed in the vehicle:

- ▷ Media: MN-1.21.6
- ▷ Phone: TN-1.21.15